

User Manual


Coating Thickness Gauge v1.0.4

1. Introduction

The thickness gauge can continuously measure the thickness of the metallic surface and the thickness of the surface of ferromagnetic metals (e. g., iron, nickel, cobalt, etc.). The specific uses of the instrument include measuring the thickness of iron, stainless steel surface paint or galvanized coating, and measuring the thickness of aluminum, copper surface paint or plastic film.

This instrument is suitable for car paint detection: while measuring the paint thickness, it can also identify the iron-galvanized and iron powder putty material. The instrument has strong anti-interference ability and can work normally in a more complex electromagnetic field environment.

2. Appearance diagram



- ① OLED display screen
- ② Green indicator light
- ③ Red indicator light
- ④ LCD display screen
- ⑤ Button
- ⑥ Anti-skid groove
- ⑦ Probe
- ⑧ Lanyard hole
- ⑨ Battery compartment
- ⑩ USB interface

3. Precautions

3.1 Battery installation

- (1) Install the battery according to the positive and negative electrode inside the battery compartment.
- (2) After loading the battery, please hold up the battery cover tightly to avoid the battery from popping up.
- (3) When the instrument is not used for a long time, please be sure to remove the battery and place it properly.

3.2 Other

- (1) Avoid direct contact with corrosive chemicals.
- (2) Avoid the use in a strong magnetic field environment (such as near the magnet) to avoid damage to the probe.
- (3) Strictly prevent strong electric and electrostatic impact.

4. Switch machine

- (1) **Power on:** one-key boot, just press the button to turn on.
- (2) **Power off:** long press for shutdown for 3 seconds; after 2 minutes without any operation (press the button or measure), the instrument will be automatically shutdown.

5. Display

- (1) **Screen brightness:** In case of no operation, the instrument will automatically dim the screen brightness after 30 seconds to extend the battery life.
- (2) **Screen rotation:** hold the button and hold (do not let go when the screen pop-up menu configuration interface) until the screen rotates 180°.
- (3) **Substrate properties:** ① instrument interface display "iron": indicates that the instrument identified the ferromagnetic metal substrate. ② The instrument interface displays "non-iron": indicates that the instrument identifies a non-ferromagnetic metal substrate. ③ The instrument interface displays "iron zinc" with a blue backlight reminder, indicating that the instrument identified the iron galvanized substrate. ④ The instrument interface shows the "iron powder putty" and has a red backlight reminder, indicating that the instrument identifies the iron powder putty substrate.
- (4) **Indicator light prompt:** ① Bright green indicator light when the measurement data is normal. ② When exceeds the measurement range or the instrument identifies the iron powder putty substrate.

6. Zero

When the instrument is used for the first time, after changing the battery, changing the measuring material or changing the ambient temperature suddenly, in order to reduce the measurement error, the zero adjustment operation should be performed. If the accuracy requirement is small, then the attached standard substrate can be zero. If the accuracy requirement is high, it is recommended to grind off the measured coating (plating) layer, and zero it on the exposed metal surface.

(1) When the instrument adjusts the standard substrate or metal surface at zero time, press the button not to let go, and immediately press the probe vertically on the substrate or metal surface, to keep the probe stable, do not tilt or shake.

(2) When the word "calibration completed" appears on the display interface, lift the instrument away from the standard substrate or metal surface and release the button.

Note: Press and hold the button for more than 3 seconds. If there is no calibration action, the instrument shutdown will be triggered.

7. Measurement steps

Step 1. Prepare the parts to be tested.

Step 2. Keep the probe end at least 2cm away from the metal object, and press the button to start on.

Step 3. The probe end quickly fits to the surface of the measured material, keep the probe stable, do not tilt or shake, in the process of the contraction of the probe into the instrument, the instrument can automatically distinguish the substrate properties and measure the thickness of the coating (plating) layer. After the displayed thickness value is refreshed and accompanied by the "drop" sound prompt, lift the instrument so that the probe end distance from the surface of the measured object is at least 2cm, then the next measurement can be made.

8. Function settings

How to enter the configuration menu interface: during the boot, press and hold the button until the screen popup, under which the function of the instrument can be set.

The method to set one of the functions: short press the button, select the corresponding function, wait for about 3 seconds, the instrument will complete the relevant function setting. The specific functions are as follows:

8.1 Probe mode

(1)**Automatic:** The instrument will make an adaptive measurement, and this mode is suitable for the unknown metal substrate.

(2)**Magnetism:** The instrument will be measured in a magnetic induction mode suitable for ferromagnetic metal substrates.

(3)**Vortex current:** The instrument will be measured in an eddy current effect mode, which is suitable for non-ferromagnetic metal substrates.

Note: the factory default "automatic" mode, can identify iron, non-iron, iron galvanized and iron powder putty substrate.

8.2 Unit

µm, mm and mil.

8.3 Language

It is available in multiple languages.

8.4 Restore the factory settings

Select the "reset" option in the configuration menu interface, and select until the word "success" appears, then the setting is completed.

8.5 Bluetooth

Select Bluetooth ON or Off.

Note: When not using Bluetooth function, you can choose "off" to reduce power consumption and prolong battery life.

9. Record and view the data

9.1 Record the data

The instrument can store 1,300 data and view up to 10 data on the instrument. Other more data needs to be connected to the APP or PC-side software to view. The instrument display interface can record up to 10 data. If there are more than 10 data, the instrument will automatically update the latest data and discard the oldest data. These data shutdown is not lost, restore the factory settings can be cleared.

9.2 View the data

(1)Check it directly on the instrument

In the measurement interface, you can browse the data one by one. The viewing data includes the latest measurement values (up to 10), and its number, maximum, minimum and average.

(2) Check it through the mobile phone APP

Open the mobile phone APP software and connect to the instrument via Bluetooth. The real-time measurement data, statistics, and data curves or bar charts can be viewed in the real-time data interface of the APP. Relevant data can also be exported through the APP.

(3) Check through the PC-end software

The instrument has the USB data transmission function, the instrument and the computer through the USB cable connection. Real-time measurement data, statistics, and data curves or bar charts can be viewed in the data interface of the computer software. Data can also be exported through the software.

10. Use of the related software

APP

(1)The APP software used in the instrument can be scanned with the QR code on the APP manual or obtained from the dealer.

(2)The software introduction and its use method can be viewed in the following steps: Open the APP> click "Help" in the lower right corner> click "APP Help Document" to view.

Note: Before Bluetooth matching and connection, you must open the instrument Bluetooth, mobile phone Bluetooth and mobile phone positioning function.

PC software

(1)The PC end software used in the instrument can obtain the software installation package from the dealer.

(2)The software introduction and its use method can be viewed according to the following steps: open the software> click "About Us" on the right side of the interface> click "Help Document" to view.

11.Function and Technical parameters

Measurement principle	Fe: Magnetic Induction; NFe: Eddy Current
Measurement range	0~2000µm
Accuracy	±(2%+1µm)
Resolution	0.1µm(0~99.9µm); 1µm(≥100µm)
Calibration	Zero calibration
Unit	µm, mm, mil
Minimum curvature radius	Convex 5mm; Concave 25mm
Minimum thickness of substrate	Fe: 0.20mm; NFe: 0.03mm
Minimum measuring area	Diameter 15mm
Measure reaction time	Less than 0.5s
Display	LCD and OLED
Bluetooth and APP	Support
USB data transfer	Support
Operating temperature	-40~50°C (OLED) ,-20~50°C (LCD)
Storage temperature	-50~60°C
Power supply	2 AAA 1.5V alkaline batteries 2 AAA 1.2V rechargeable batteries
Protection level	IP40
Demension	103*64*25mm
Shell material	ABS
Weight	About 60g(without batteries)